




EASA AP-DOA, Schválenie č. AP356
EASA AP-DOA, Approval No. AP356

ZOZNAM PRÍKAZOV K ZACHOVANIU LETOVEJ SPOSOBILOSTI (AD) A SERVISNÝCH BULLETINOV (SB) PRE WT9 DYNAMIC LSA

LIST OF AIRWORTHINESS DIRECTIVES (AD) AND SERVICE BULLETINS (SB) FOR WT9 DYNAMIC LSA

Formulár / Form: DO-FORM9-100.1	Typ. osvedčenie / TCDS EASA.A.644	Typ / Type WT9 Dynamic LSA	Model / Model: Club	V. č. lietadla/ Airplane S/N:	Reg. značka / Reg. No.:
---	---	--------------------------------------	-------------------------------	-------------------------------	-------------------------

EASA AD, dátum vydania: EASA AD, date of issue:	SB, dátum vydania: SB, date of issue:	Dotknuté lietadlá: Affected aircrafts:	Predmet: Subject:	Vykonať do: Compliance:	Vykonaný: Complied:
-	SBRTC-2019-1, Initial issue, 16.04.2019	17001 to 19002 inclusive.	Possible retrofit of Major Design Change - Propeller KW-31 and towing equipment. Major Change approval No. 10070607.	Optional.	
-	SBRTC-2019-2, Initial issue, 29.07.2019	17001 to 19003 inclusive.	Replacement of circlip (carburetor) for Rotax Engine Type 912.	Within next 25 hr. The latest by July 31 st 2020.	
-	SBRTC-2020-1, Initial issue, 10.03.2020	All S/N equipped with AVE-WPSTR/G-20D MOD(1) lights.	Replacement of the original AVE-WPSTR/G-20D MOD(1) Navigation / Position / Strobe LED Lights by the AVE-WPSTR/G-20D MOD(2). Minor Change approval No. 10072698.	Optional.	
-	SBRTC-2020-2, Revision 1, 14.04.2020	17001 to 20001 inclusive.	Change of brake hoses connection to the calipers. Minor Change approval No. 10072698.	Mandatory. At next brake fluid change.	
-	SBRTC-2020-3, Initial issue, 10.03.2020	All S/N equipped with ELT Kannad 406 AF-COMPACT unit.	Replacement of ELT Kannad 406 AF-COMPACT unit by the ELT Kannad AF INTEGRA unit. Minor Change approval No. 10072699.	Optional.	
-	SBRTC-2020-4, Revision 1, 13.08.2020	17001 to 20005 inclusive.	Inspection of gap between the elevator root hinge assembly and the vertical stabilizer. Minor Repair approval No. 10073878.	Mandatory. At next periodic inspection.	

 EASA AP-DOA, Schválenie č. AP356 EASA AP-DOA, Approval No. AP356	ZOZNAM PRÍKAZOV K ZACHOVANIU LETOVEJ SPOSOBILOSTI (AD) A SERVISNÝCH BULLETINOV (SB) PRE WT9 DYNAMIC LSA LIST OF AIRWORTHINESS DIRECTIVES (AD) AND SERVICE BULLETINS (SB) FOR WT9 DYNAMIC LSA				
	Formulár / Form: DO-FORM9-100.1	Typ. osvedčenie / TCDS EASA.A.644	Typ / Type WT9 Dynamic LSA	Model / Model: Club	V. č. lietadla/ Airplane S/N:

EASA AD, dátum vydania: EASA AD, date of issue:	SB, dátum vydania: SB, date of issue:	Dotknuté lietadlá: Affected aircrafts:	Predmet: Subject:	Vykonať do: Compliance:	Vykonaný: Complied:
-	SBRTC-2020-9, Initial issue, 21.12.2020	All aircraft from S/N 17001 up to S/N 19003 inclusive, or aircraft equipped with carburetors and spare parts according to Rotax Service Bulletin SB-912-074UL / SB-914-056UL / SB-2ST-004.	Exchange of carburetor floats (pair) on Rotax 912 engines.	Mandatory. At next periodic inspection.	
-	SBRTC-2019-3, Initial issue, 25.01.2021	17001 to 20005 inclusive.	Possible retrofit of Major Design Change – Transponder Garmin GTX 335 with ADS-B Out. Major Change approval No. 10075449.	Optional.	
-	SBRTC-2019-4, Initial issue, 25.01.2021	17001 to 20005 inclusive.	Update of Dynon SkyView firmware to version 15.4.7. Major Change approval No. 10075449.	Mandatory. At next periodic inspection.	
-	SBRTC-2020-5, Initial issue, 25.01.2021	All S/N equipped with fuel pressure sensor ROAD.	Replacement of fuel pressure sensor ROAD unit by fuel pressure sensor KAVLICO. Minor Change approval No. 10073873	Optional.	
-	SBRTC-2020-6, Initial issue, 25.01.2021	All S/N.	Equivalent oil hoses CONTI OLNS1 (Rotax P/N 956390) and CONTI M4M-2 (Rotax P/N 956394). Minor Change approval No. 10073873	Information.	



EASA AP-DOA, Schválenie č. AP356
EASA AP-DOA, Approval No. AP356

ZOZNAM PRÍKAZOV K ZACHOVANIU LETOVEJ SPOSOBILOSTI (AD) A SERVISNÝCH BULLETINOV (SB) PRE WT9 DYNAMIC LSA

LIST OF AIRWORTHINESS DIRECTIVES (AD) AND SERVICE BULLETINS (SB) FOR WT9 DYNAMIC LSA

Formulár / Form: DO-FORM9-100.1	Typ. osvedčenie / TCDS EASA.A.644	Typ / Type WT9 Dynamic LSA	Model / Model: Club	V. č. lietadla/ Airplane S/N:	Reg. značka / Reg. No.:
---	---	--------------------------------------	-------------------------------	-------------------------------	-------------------------

EASA AD, dátum vydania: EASA AD, date of issue:	SB, dátum vydania: SB, date of issue:	Dotknuté lietadlá: Affected aircrafts:	Predmet: Subject:	Vykonať do: Compliance:	Vykonaný: Complied:
-	SBRTC-2020-7, Initial issue, 25.01.2021	All S/N equipped with TRX-1500.	Modification of traffic information system from TRX-1500 to AT-1. Minor Change approval No. 10074200.	Optional.	
-	Cancelled: SBRTC-2020-8, Initial issue, 01.02.2021 Superseded by: SBTC-2021-2	17001 to 20005 inclusive.	Replacement of throttle controller with simple throttle controller. Minor Change approval No. 10075525.	Optional.	
-	SBTC-2021-1 Revision 1, 11.08.2021	17001 to 21002 inclusive, DY-444/2012 LSA	Update of Pilot's Operating Handbook, updated maintenance instructions to Aircraft Maintenance Manual and replacement of interior placards. Minor Change approval No. 10076975.	Mandatory. At next periodic inspection.	
-	SBTC-2021-2 Initial issue, 02.08.2021	All S/N.	Installation of optional throttle controller. Minor Change approval No. 10076975.	Optional.	
	SBTC-2022-1, Revision 1, 11.07.2022	22001	Replacement of push rod end bearings in elevator and aileron control system.	Mandatory.	

Kontroloval:
Inspected by:

.....
Meno, dátum, podpis
Name, date, signature