

# SERVICE BULLETIN SBLSA-017-2021

Revision: 0

Date: 23.03.2021

This Service bulletin has been produced in accordance with approved Alternative Procedures to DOA EASA.AP356.

Technical data has been approved by EASA under Approval No.:

☐ INFORMATION

☐ RECOMMENDED

**⋈** MANDATORY

#### A. SUBJECT:

Inspection of propeller SR2000DN installed at the aircraft WT9 Dynamic LSA.

#### **B. AFFECTED AIRPLANES:**

Aircraft with installed propeller's S/N: 260120, 46083, 11054, 06065

## C. REASON:

Occurrence of a propeller blade separation during the engine ground test.

## D. REQUIRED ACTION:

The propeller inspection at propeller manufacturer Woodcomp Propellers s. r. o.

- 1. Remove the propeller from the aircraft according to Aircraft Maintenance Manual.
- 2. Send the propeller to propeller's manufacturer:

Woodcomp Propellers s. r. o.

Vodolská 4

250 70, Odolena Voda

**Czech Republic** 

- 3. After the inspection inform the aircraft manufacturer via email <a href="mailto:airworthiness@aerospool.sk">airworthiness@aerospool.sk</a> about:
  - S/N of aircraft
  - S/N of propeller
  - Operating time of the propeller
  - Findings of the inspection
- 4. Install the propeller to the aircraft according to Aircraft Maintenance Manual.

#### E. COMPLIANCE:

Before next flight.

# F. WEIGHT AND BALANCE:

None.

# G. ACTION CARRIED OUT BY:

Propeller removal/installation:

Approved Maintenance Organisation, Part-66 qualified maintenance personnel.

Propeller inspection:

Propeller manufacturer Woodcomp Propellers s. r. o. (<a href="http://www.woodcomp.cz/contact/">http://www.woodcomp.cz/contact/</a>).

# H. COSTS COVERED BY:

- Transport charges will be covered by aircraft owner.
- The costs relative to special inspection will be covered by propeller manufacturer Woodcomp Propellers s. r. o.

## I. <u>NECESSARY MATERIAL:</u>

None.



# SERVICE BULLETIN SBLSA-017-2021

Revision:	0
Date:	23 03 2024

This Service bulletin has been produced in accordance with approved Alternative Procedures to DOA EASA.AP356.

Technical data has been approved by EASA under Approval No.:

☐ INFORMATION ☐ RECOMMENDED ☑ MANDATORY

## J. <u>DOCUMENTATION:</u>

#### Refer to:

- AS-AMM-10-000, Aircraft Maintenance Manual
- Technical Description, Operating, Maintenance and Repair manual for WT9 Dynamic LSA
- Woodcomp Propellers Operator's Manual, Electrical adjustable aircraft propeller SR 2000, latest revision

# K. **ENCLOSURES**:

None.

## L. APPROVAL:

Vladimír Martinák

Head of Design Organisation

Position, Name, Signature

/ Jozet Snire

Technical Director
Position, Name, Signature