

This Service Bulletin has been produced in accordance with approved Alternative Procedures to DOA EASA.AP356.

INFORMATION

RECOMMENDED

MANDATORY

This Service Bulletin revises SBLSA-930-2021, Revision 0, dated 25.01.2021.

A. SUBJECT:

Transition of the WT9 Dynamic LSA aircraft from PtF to the CofA.

B. AFFECTED AIRPLANES:

DY-444/2012 LSA

C. REASON:

In accordance with the EASA document "Transition period for LSA aircraft under Permit to Fly", Aerospool spol. s r. o. issues this Service Bulletin to modify the aircraft in order to transfer the subjected aircraft from PtF to the CofA.

For that purpose, the modifications listed in the section "D" must be performed.

D. REQUIRED ACTION:

Perform the modifications on the aircraft according to attached list.

1. Installation of flanges for strainers into the fuel tank ribs according to procedures TC-D531-1 and TC-D000-1.
2. Installation of fuel strainers in the fuel tank ribs according to the procedure TC-D282-1.
3. Replacement of production ID according to procedure TC-D113-1.
4. Performing aircraft adjustment, equipment calibration and tests according to the procedure TC-D000-2.
5. Equipment of the aircraft by set of new documentation stated in section J.

E. COMPLIANCE:

Until 20th December 2021.

F. WEIGHT AND BALANCE:

Weight change: Determine by weighing after modification.

Moment change: Determine by weighing after modification.

G. ACTION CARRIED OUT BY:

Approved Maintenance Organization.

H. COSTS COVERED BY:

Aircraft owner:

I. NECESSARY MATERIAL:

Necessary material will be supplied by aircraft manufacturer Aerospool, spol. s r. o.

This Service Bulletin has been produced in accordance with approved Alternative Procedures to DOA EASA.AP356.

 INFORMATION **RECOMMENDED** MANDATORY**J. DOCUMENTATION:**

AS-POH-01-000	Pilot's Operating Handbook, R4
AS-POH-01-001	Supplement No. 001 - Equipment List 1, R4
AS-POH-01-003	Supplement No. 003 - Propeller KW-31 / Towing Operation, R2
AS-POH-01-004	Supplement No. 004 - Garmin GNC 255A NAV/COMM, Initial issue
AS-POH-01-006	Supplement No. 006 - PM3000 Intercom, Initial issue
AS-POH-01-010	Supplement No. 010 - Garmin GTX 335 XPDR, Initial issue
AS-POH-01-011	Supplement No. 011 - KANNAD AF INTEGRA ELT, Initial issue
AS-AMM-01-000	Aircraft Maintenance Manual, R4
AS-AWM-01-000	Aircraft Wiring Manual, R4

K. ENCLOSURES:

None.

L. APPROVAL:

This Service Bulletin was issued on the base of Minor Change Approval No. 10075666.



Vladimír Martinák
Head of Design Organisation

Position, Name, Signature



Jozef Šnitc
Technical Director

Position, Name, Signature