

This Service Bulletin has been produced in accordance with approved Alternative Procedures to DOA EASA.AP356.

☐ INFORMATION☒ **OPTIONAL/RECOMMENDED**☐ MANDATORY**A. SUBJECT:**

Replacement of throttle controller with simple throttle controller.

B. AFFECTED AIRPLANES:

From S/N 17001 up to S/N 20005 inclusive.

C. REASON:

For easier operation of the throttle controller (especially during training flights) there is a possibility to install a simple throttle controller. The simple throttle controller does not have the rotary function and center button for locking/unlocking of the controller.

D. REQUIRED ACTION:

1. Remove the throttle controller. For removal procedure refer to AS-AMM-01-000, latest revision, Chapter 76-10.
2. Install the simple throttle controller. For installation procedure refer to AS-AMM-01-000, latest revision, Chapter 76-10.
3. Perform the engine ground test according to POH.
4. Record the compliance with this bulletin into aircraft documentation.

E. COMPLIANCE:

Optional.

F. WEIGHT AND BALANCE:

Weight change: Negligible.

Moment change: Negligible.

G. ACTION CARRIED OUT BY:

Approved Maintenance Organization.

H. COSTS COVERED BY:

Costs covered by aircraft owner.

This Service Bulletin has been produced in accordance with approved Alternative Procedures to DOA EASA.AP356.

☐ INFORMATION☒ **OPTIONAL/RECOMMENDED**☐ MANDATORY**I. NECESSARY MATERIAL:**

Necessary material will be supplied on request by aircraft manufacturer Aerospool, spol. s r. o. For material purchase contact the airplane manufacturer's directly at spareparts@aerospool.sk.

Item	Part Name	Part Number	Quantity
1	SBRTC-2020-8 KIT	SBRTC-2020-8	1 pc

Part Number SBRTC-2020-8 contains:

Item	Part Name	Part Number	Quantity
1	THROTTLE CONTROLLER 2	D76100100B	1 pc
2	Safety wire Ø0.8 mm	N3725-004	1 m
3	Cable tie 2.6	N4327-003	10 pcs
4	Cable tie 4.8	N4327-007	10 pcs
5	SELF-LOCKING NUT M5	N3222-005	2 pcs

J. DOCUMENTATION:



AS-AMM-01-000 Aircraft Maintenance Manual, Rev. 5 or later approved revision

K. ENCLOSURES:

None.

L. APPROVAL:

This Service Bulletin was issued on the base of Minor Change Approval No. 10075525.

 Vladimír Martinák Head of Design Organisation Position, Name, Signature	 Jozef Šnirc Technical Director Position, Name, Signature
--	---