

Subject: Change of Time between overhaul intervals (TBO) of Woodcomp propellers

Affected: WT-9 Dynamic, all serial numbers and models fitted with Woodcomp propellers

Compliance: Immediately

Mass data: Weight change – none
Moment change – none

Reason: Woodcomp Service bulletin No. 02/2012 EN issued on November 08, 2012 (see enclosures)

Arrangements: Verify Woodcomp propellers operation hours and operation time

Material: None

Documentation: Perform a manual correction of TBO intervals in WT-9 Dynamic Flight manual, Maintenance and repair manual and propeller operation and repair manual

Enclosures: Woodcomp Service bulletin No.02/2012 EN issued on November 08, 2012

Prievidza November 26, 2012

Issued:

Approved: 11. DEC. 2012

Act no. 11789/2012/OUV

Approved by: CAA of Slovak republic

