

Subject: Change in the WT-9 Dynamic Flight Manual and Maintenance Manual (change in MTOW data for 472.5 kg - concerns the aircraft fitted with rescue system and registered under Slovak CAA, change in crosswind velocity for 12.4 m/s or 24 knots and completion of a missing airframe annual periodical inspection data)

Affected: WT-9 Dynamic, all serial numbers and models

Compliance: At the next periodical inspection of the plane

Mass data: Weight change – none
Moment change – none

Reason: Listed changes are resulting from WT-9 Dynamic operation and in order to synchronize aircraft manuals and legislative requirements in force

Arrangements: In the Flight Manual replace pages 0-1,2 1-2, 2-5, 7, 4-12,13 and 5-2,3,4,5 with new ones dated from September 12, 2011, Rev. No. 10 (for the model with fixed undercarriage) and Rev. No.11 (for the model with retractable undercarriage)
In the Operating, Maintenance and Repair Manual replace pages 0-2,3, 1-3,6 and 3-3 with new ones dated from September 12, 2011, Revision 7

Material information: Changed pages 0-1,2 1-2, 2-5,7, 4-12,13 and 5-2,3,4,5 of the Flight Manual and changed pages 0-2,3, 1-3,6 and 3-3 of the Operating, Maintenance and Repair Manual are in appendix to this Bulletin.

Documentation:

- Make note about the change in Flight Manual, page 0-1, "Record of revisions" and page 0-2 "List of effective pages"
- Make note about the change in Operating, Maintenance and Repair Manual, page 0-2, "Record of revisions" and 0-3 "List of effective pages"

Prievidza, September 12, 2011

Issued:

AEROSPOOL spol. s r.o.
Approval L-2-012/SK 2007
971 03 PRIEVIDZA
SLOVAK REPUBLIC

Approved:

Approved by:


27. OKT. 2011

CAA of Slovak republic

