



**SERVICE BULLETIN  
SBRTC-2020-8**

Revision: **Initial**

Date: **01.02.2021**

This Service Bulletin has been produced in accordance with approved Alternative Procedures to DOA EASA.AP356.

INFORMATION

**OPTIONAL/RECOMMENDED**

MANDATORY

**A. SUBJECT:**

Replacement of throttle controller with simple throttle controller.

**B. AFFECTED AIRPLANES:**

From S/N 17001 up to S/N 20005 inclusive.

**C. REASON:**

For easier operation of the throttle controller (especially during training flights) there is a possibility to install a simple throttle controller. The simple throttle controller does not have the rotary function and center button for locking/unlocking of the controller.

**D. REQUIRED ACTION:**

1. Remove the throttle controller. For removal procedure refer to AS-AMM-01-000, latest revision, Chapter 6-1.
2. Install the simple throttle controller. For installation procedure refer to AS-AMM-01-000, latest revision, Chapter 76-10.
3. Perform the engine ground test according to POH.
4. Record the compliance with this bulletin into aircraft documentation.

**E. COMPLIANCE:**

Optional.

**F. WEIGHT AND BALANCE:**

Weight change: Negligible.

Moment change: Negligible.

**G. ACTION CARRIED OUT BY:**

Approved Maintenance Organization.

**H. COSTS COVERED BY:**

Costs covered by aircraft owner.

**CANCELLED**  
**Superseded by**  
**SBRTC-2021-2,**  
**the latest revision**



# SERVICE BULLETIN SBRTC-2020-8

Revision: **Initial**

Date: **01.02.2021**

This Service Bulletin has been produced in accordance with approved Alternative Procedures to DOA EASA.AP356.

INFORMATION       **OPTIONAL/RECOMMENDED**       MANDATORY

### I. **NECESSARY MATERIAL:**

Necessary material will be supplied on request by aircraft manufacturer Aerospool, spol. s r. o. For material purchase contact the airplane manufacturer's directly at [spareparts@aerospool.sk](mailto:spareparts@aerospool.sk).

Item	Part Name	Part Number	Quantity
1	SBRTC-2020-8 KIT	SBRTC-2020-8	1 pc

Part Number SBRTC-2020-8 contains:

Item	Part Name	Part Number	Quantity
1	THROTTLE CONTROLLER 2	D76100100B	1 pc
2	Safety wire Ø0.8 mm	N3725-004	1 m
3	Cable tie 2.6	N4327-003	10 pcs
4	Cable tie 4.8	N4327-007	10 pcs
5	SELF-LOCKING NUT M5	N5222-005	2 pcs

# CANCELLED

### J. **DOCUMENTATION:**

AS-AMM-01-000 Aircraft Maintenance Manual, Rev. 5 or later approved revision

### K. **ENCLOSURES:**

None.

### L. **APPROVAL:**

This Service Bulletin was issued on the basis of Minor Change Approval No. 10075525.

 Vladimír Marhaňák Head of Design Organization	 Jozef Štráček Technical Director
Position, Name, Signature	Position, Name, Signature

# Superseded by SBTC-2021-2, the latest revision