



ZOZNAM SERVISNÝCH BULLETINOV PRE WT 9 600 (MTOW 600 kg)
LIST OF SERVICE BULLETINS FOR WT 9 600 (MTOW 600 kg)

Formulár / Form: NDO-FORM9-100.1	Typ. osvedčenie / TCDS	Typ / Type	Model / Model:	V. č. lietadla/ Airplane S/N:	Reg. značka / Reg. No.:
-					

Č. SB, revízia, dátum: SB No., revision, date:	Dotknuté lietadlá: Affected aircraft:	Predmet: Subject:	Vykonať do: Compliance:	Vykonaný: Complied:
SB600-2020-1, Initial issue, 28.08.2020	DY-697; DY-698D; DY-700D; DY-705D	Inspection of gap between the elevator root hinge assembly and the vertical stabilizer skin.	At the next periodic inspection.	
SB600-2020-2, Initial issue, 28.08.2020	DY-700D	Replacement of the main and auxiliary fuel pump check valves on the aircraft equipped with engine Rotax 914UL.	At the next periodic inspection.	
SB600-2020-3, Initial issue, 21.12.2020	DY-685; DY-695; DY-700D; DY-705D; DY-709D; DY-713D	Installation of parachute front spacer between firewall and parachute fabric container.	At the next periodic inspection.	
SB600-2021-1, Initial issue, 12.03.2021	DY-724D	Engine mount inspection of aircraft with fixed landing gear and engine Rotax 912 iS	At the next periodic inspection.	
SB600-2022-1, Revision 2, 13.07.2022	DY-766D; DY-768D; DY-771D	Replacement of push rod end bearings in elevator and aileron control system.	Before next flight.	



ZOZNAM SERVISNÝCH BULLETINOV PRE WT 9 600 (MTOW 600 kg)
LIST OF SERVICE BULLETINS FOR WT 9 600 (MTOW 600 kg)

Formulár / Form: NDO-FORM9-100.1	Typ. osvedčenie / TCDS	Typ / Type	Model / Model:	V. č. lietadla/ Airplane S/N:	Reg. značka / Reg. No.:
-					

Č. SB, revízia, dátum: SB No., revision, date:	Dotknuté lietadlá: Affected aircraft:	Predmet: Subject:	Vykonať do: Compliance:	Vykonaný: Complied:
SB600-2024-1, Initial issue, 09.02.2024	All aircraft	Inspection of the emergency parachute cover.	Before next flight.	

Kontroloval:
Inspected by:

.....
Meno, dátum, podpis
Name, date, signature